

TES-3040 AC Clamp Meter



Features

- ◆ 3-3/4 Digital LCD with bar-graph
- ◆ Auto-power off with Data Hold & MAX/MIN mode
- ◆ Zero Adjustment/Relative Reading

- **Current:** (AC)
400/1,000A
- **Voltage:** (AC/DC)
DC-400mV/4V/40V/400V/600V
AC-4V/40V/400V/600V
- **Resistance:** (Ohm)
400Ω/4KΩ/40KΩ/400KΩ/
4MΩ/40MΩ
- **Frequency:** (Hz)
100Hz/1KHz/10KHz/100KHz/
800KHz

TES-3050 TRMS AC/DC Clamp Meter



Features

- ◆ 3-3/4 Digital LCD with bar-graph
- ◆ Auto-ranging off/Data Hold/
Peak Hold
- ◆ MAX/MIN mode
- ◆ Zero Adjustment/Relative Reading

- **Current:** (AC/DC)
400/1000A
- **Voltage:** (AC/DC)
DC-400mV/4V/40V/400V/600V
AC-4V/40V/400V/600V
- **Frequency:** (Hz)
100Hz/1KHz/10KHz/100KHz/
800KHz
- **Ohms:** (Resistance)
400Ω/4KΩ/40KΩ/400KΩ/
4MΩ/40MΩ

TES-3082 TRMS AC/DC Clamp Meter



Features

- ◆ True RMS Reading
- ◆ 4000 count Reading
- ◆ AC/DC 600A
- ◆ DCA One-touch-Zero

- **Current:** (DC/AC)
(± 1.9%rdg ± 5dpts)
400A/600A
- **Voltage:** (DC/AC)
DC-600V; AC-400V/600V
- **Resistance:** (Ohms)4KΩ
- **Frequency:** (Aurorange)
4KHz/20KHz

TES-3092 AC/DC Clamp Meter (700A AC/DC)



Features

- ◆ Compact & Pocket Size
- ◆ AC 700A & DC 800A
- ◆ 600V AC & 200V DC Ohm/
Continuity Beeper.
- ◆ One Touch DAC Zero

- **DC/AC Current:**
200A/800A (DCA)
200A/700A (ACA)
- **DC/AC Voltage:**
200V (DCV)
600V (ACV)
- **Ohms:** 2KΩ
- **Resolution:** 0.1 A/1A, 0.1V/1V